Richmond Refinery LPS Bulletin – Reliability



Turbulence induced NH₄HS Piping Leak



Impact ERM: 38022

Location:

Hydroprocessing ABU – South ISOMAX – 8 Plant

Contact Information:

Aaron Sims 510-242-1331 AVRZ@Chevron.com

AVIZ@Clievion.com

Reference:

Investigation # 23615



Washed out area between socketwelded flange and pipe.



Tenets of Operations Violated: -

Tenet #10 – Always involve the right people in decisions that affect procedures and equipment.

Incident Description:

On 5/21/2012, South Isomax operations reported a pinhole leak at a 1- ½" 150# socket welded flange to pipe weld between E-831 and LC-831 in the 8 plant (NH3-H2S Recovery Unit). The plant was shutdown to allow the leak to be isolated and repaired.

Investigation Findings:

- 1) The design gap of 1/8" between the socket welded flange and the pipe creates a crevice and a turbulent area. This service contains (ammonium bisulfide) NH₄HS, and as per API 571, NH₄HS corrosion increases with concentration and turbulence.
- 2) This circuit has an abundance of corrosion monitoring locations (CMLs), and although there is an appropriate inspection technique of radiography that can detect corrosion and thinning, the damage at this location is not able to be detected through this radiography technique (i.e., such non-intrusive inspection techniques do not work in this situation due to the location of the corrosion).
- 3) The upstream exchanger (E-831) has an Inconel bundle and downstream (E-820) inlet is fabricated from Hastelloy C-276.

Lessons Learned / Business Practices:

- 1) Crevices should be minimized in process streams with turbulent high NH₄HS concentrations.
- 2) When upgrading materials in equipment (i.e., E-831 and E-820), consideration should be given to the condition of the piping between the equipment.

What Worked Well:

1) The leak was isolated and the flange was replaced without incident.

Recommendations:

- 1) Evaluate the NH₄HS piping design criteria and redesign the system to minimize corrosion due to NH₄HS and turbulent conditions.
- 2) Make the system available for inspection in order to investigate the entire system to determine that there is no imminent leak potential in 8 plant.
- 3) Evaluate whether there is a need to inspect similar plants (e.g., at the Richmond Refinery, it is 18 plant) for similar scenarios and inspect such plants to the extent necessary.

This document is intended for company workforce only. Nothing herein should be construed as a legal determination of causation or responsibility. The company makes no representations or warranties, express or implied, about the thoroughness, accuracy, or suitability of use by others of any of the information contained herein.

For Internal Use only – Chevron Confidential

Distribution limited to Richmond Refinery personnel

Date (06 JUN 2012)